

Release Note

General information	
Issue ID Number	1-IXTPN
Product Name	Fiery EX3535 Color Server v.1.0
Issue Date	November 4, 2005

Files included in this release	
File name	File size
1-IXTPN.ps	388 Kilobytes
1-IXTPN_relnotes.doc	44 Kilobytes

Issue(s) addressed with this release

Page order of duplex stapled sets is corrupted when printing resumes after finisher is emptied.

Steps to reproduce

1. Print the test archive file to an EX3535 connected to a DC3535 with a fully configured finisher and stapler.
2. Finisher will fill up and then prompt the user to remove paper. Let job remain untouched in the finisher for about 15 min.
3. Unload paper tray and allow the job to resume printing. Note that the remaining sets will print with the pages out of order.

Installation instructions

1. Download/Import the patch file “1-IXTPN.ps” with Command Workstation to the “Direct” queue.
2. Allow the file to finish processing and wait at least 1 minute, then power down the server. Power the copier down using the power switch on the front of the copier, wait for it to shut off completely.
3. Power up the server. After the server has reached idle, power up the copier.
4. Print out the configuration page.

Verify the **Update Info** section. It should contain the patch number “1-IXTPN”.

Prerequisite(s)

N.A.

Known Issues

N.A.

