

Release Note

General information	
Issue ID Number	1-OQIAF
Product Name	DocuColor 240/250 v1.1 EFIGSPD+Nordic
Issue Date	August 28, 2006

Files included in this release	
File name	File size
1-OQIAF.ps	8,445 bytes
1-OQIAF_relnotes.doc	46,080 bytes)

Issue(s) addressed with this release

The Scan-to-mailbox feature causes engine failures including 27-741, 016-781 and 016-782.

Steps to reproduce

1. Perform Scan-to-mailbox and observe the printer lcd.
Result: Sometimes the printer enters an error condition. Some of the failures include 27-741, 016-781 and 016-782.

Prerequisite(s)

None

Installation instructions

1. Download/Import the patch file “1-OQIAF.ps” with Command Workstation to the “Direct” queue.
2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
3. From the Fiery LCD or from Command Workstation, select “Shut Down” and then “Reboot System”
4. Please wait until the Fiery has come to idle and print out the configuration page.

Verify the **Update Info** section. It should contain the patch number “1-OQIAF”.

Additional Notes

This patch is not intended to clean any current corrupted mailboxes. It changes the behavior of the polling interval to prevent further corruption.