

Product Enhancements ReadMe for WorkCentre 5325/5330/5335 Firmware 53.34.23

Release Date: July 31, 2018

dc18rn3799

Software Release Details

System Software	Version
System Software	53.34.23
Controller	1.205.159
IOT	40.2.0
ADF	7.10.0
Fax	1.1.14
A-Finisher	15.3.0
SB-Finisher	7.3.0
Link to Software	WC5325/5330/5335

I. Fixes/Features new in this release

- Fixed the issue when GRAYSCALE is combined with searchable PDF and fails with Fault Code 016-776 when originals contain blank pages.
- Fixed the issue to successfully scan to a cloud based Nutanix server via SMB
- Fixed the issue when Cirrato authentication with TWN4 MIFARE NFC-p USB card reader stops working after a while.
- Fixed an issue when unable to authenticate with swipe card after the wake up. A reboot was necessary for swipe card login to work but alternate login remained working.
- The 3DES encryption protocol has been removed, which removes the possibility of the vulnerability known as Sweet32 (CVE 2016-2183) from being exploited.

II. Installation Notes

Install instructions are included in the zip file containing firmware. Unzip and download before attempting to install the firmware

III. Additional Details

- This release contains no new features

© 2018 Xerox Corporation. All rights reserved. Xerox®, Xerox and Design®, and WorkCentre® are trademarks of Xerox Corporation in the United States and/or other countries. BR22773

Other company trademarks are also acknowledged. Document Version: 1.0 (January 2018).