DocuColor 242/252/260 Integrated Fiery Color Server **xerox**

Xerox Corporation 800 Phillips Road Webster, NY 14580

February 2013

Dear Xerox DocuColor 242/252/260 Integrated Fiery Color Server customer:

Your DocuColor 242/252/260 Integrated Fiery Color Server can now be upgraded with the 1-1IJ6ZK software patch.

NOTE: Your system must be at version 2.0 prior to installing this software.

We tested this software patch specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software patch contains fixes for the following SPARs:

SPAR#		Description
1.	195844632	Fiery patch to address security vulnerabilities.
		Apache = 2.2.23 PHP = 5.3.19 Mod_ssl = 2.2.23 OpenSSL = 0.9.8x

Prerequisites:

- PRODID
- 1-U8E58
- 1-18SMZM
- 1-1E21N4
- 1-13LK3J
- 1-19AZVM
- 1-1CNL1W
- 1-1H1YIQ
- 1-1FLFQA

NOTE: For those customers that do NOT use EFI Auto-Updates and do NOT use FreeFlow® the following patch configuration is to be considered the minimum required. If at a later time the customer decides to add FreeFlow® or enable EFI Auto-Updates, a complete reload of the Fiery to the above configuration will be required.

- PRODID
- 1-U8E58
- 1-18SMZM
- 1-1E21N4
- 1-1H1YIQ

1-1IJ6ZK 1 of 1