

ReadMe for Xerox® Phaser 3330

Firmware 61.003.00.000

Release Date: June 27, 2018

dc18rn3789

Software Release Details

Component	Version
System	61.003.00.000
MCB	V2.50.03.00
Engine(IOT)	V0.00.39_V1.00
Network	4.00.50.69
Link to Software	Phaser 3330

I. Fixes/Features new in this release

- Fixed a bug with image shifting and cutting off part of the image on custom size output
- Updates to support Blue Angle power requirements

II. Installation Notes

Install instructions are included in the zip file containing firmware. Unzip and download before attempting to install the firmware

III. Fixes / Features from previous releases

- Fixed PH3330 menu map strings to completely translate Hungarian Language
- Fixed issue when printing to the printer via Mopria on a WiFi Direct connection, jobs over 256kb in size prints out a corrupted job error sheet
- Drops off Wi-Fi network when deep sleep, machines need reboot to get back online
- 3K toner support for DMO
- Tray1 is the default tray, customer requires By-pass be default.
Special Instructions:
 - When SFO Key 60 is set to enabled the default paper source will be the bypass tray.
 - When SFO key 60 is set to disabled the default paper source will be tray 1.
 - To enable/disable an SFO select the Menu hard button on the device.
 - Navigate to Tools and enter system administrator credentials
 - Select Special Feature Options and enter the SFO number.
- UI displays : " more than 45 days left" in spite of supplies plan being set correctly

© 2018 Xerox Corporation. All rights reserved. Xerox®, Xerox and Design®, and WorkCentre® are trademarks of Xerox Corporation in the United States and/or other countries. BR22773
Other company trademarks are also acknowledged. Document Version: 1.0 (January 2018).