RELEASE NOTES

General information	
Issue ID Number	1-DSRD9
Product Name	Fiery on XPe Operating System, languages EFIGSBPD
Issue Date	29 April 2004

Files included in this release	
File name	**File size**
1-DSRD9.ps	27.3 MB
Relnotes.PDF	

Issue description
Problems Addressed:
1. XPe cumulative security patch for Fiery running on XPe in languages EFIGSBPD.

Steps to reproduce
n/a

Resolution type:	Closed - Patch

Resolution
1-DSRD9.ps

Important notes

Installation Instructions:
1. Download 1-DSRD9.ps file via the Fiery Downloader or Command Workstation to the "Direct" Queue.
2) After the system returns to 'Idle", wait 60 seconds.
3) Reboot the Print Controller. If your Fiery has an LCD, choose Shut Down, and choose "Reboot System". If your Fiery Does not have an LCD, use the Windows Start/Shut Down/Restart menu. Turn off your copier.
4) Let Print Controller come to idle.
5) Print the configuration page and make sure the correct information appears (Update Info section should contain the patch number 1-DSRD9.

Important Note: This patch installs the following MS hotfixes on the Fiery:

QFE#	MS Patch	Description
824146	MS03-039	Remote Procedure Call Service Update
330994	MS03-014	Cumulative Patch for Outlook Express
823559	MS03-023	Buffer Overrun in HTML Converter Could Allow Code execution
815021	MS03-007	Unchecked Buffer In Windows Component Could Cause Server Compromise
828750	MS03-040	Cumulative Update for Internet Explorer
823182	MS03-041	Vulnerability in Authenticode Verification could allow Remote Code Execution
828035	MS03-043	Buffer Overrun in Messenger Service Could Allow Code Execution
819696	MS03-030	Unchecked Buffer in DirectX Could Enable System Compromise
825119	MS03-044	Buffer Overrun in Windows Help Support Cntr Could Lead to System Compromise
824105	MS03-034	Flaw in NetBIOS Could Lead to Information Disclosure
832894	MS04-004	Cumulative Security Update for Internet Explorer
828028	MS04-007	MS Bulletin MS04-007 ASN.1 Vulnerability Could Allow Code Execution
835732	MS04-011	April 2004: Security Update for Windows XP Embedded with SP1 (835732)
832483	MS04-003	Buffer Overrun in MDAC Function Could Allow Code Execution
824141	MS03-045	Buffer Overrun in the ListBox and in the ComboBox Control Could Allow Code Execution
821557	MS03-027	Unchecked Buffer in Windows Shell Could Enable System Compromise