

***Lines Missing
EX12 2.0 & EX12 2.0 SP2***

Problems Addressed:

Lines missing with imported objects after calibration. (Xerox SPAR # 15681469, EFI Bug # 1-DJA3Q)

Solution:

Download the enclosed 1-DJA3Q.ps to the Fiery.

This update consists of the following file:

File Name	File Size
1-DJA3Q.ps	2.94 KB

Installation Instructions:

1. Download 1-DJA3Q.ps file via the Fiery Downloader, Web Downloader or Command WorkStation to the Print queue or Direct Connection.
Note: Downloading via Command WorkStation, refer to the Job Management Guide, Page 3-7
Downloading via Fiery Downloader, refer to the Printing Guide, Page 4-4
Accessing the Web Downloader, refer to the Printing Guide, Page 9-2
2. Wait 60 seconds.
3. Reboot the Fiery server from the Fiery Control Panel.
4. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-DJA3Q.