

***Duplexing to Mailbox with Odd Number Pages***  
***EX12 v2.0***

**Problems Addressed:**

Printing an odd number pages to the Mailbox Bin will result with the last page printing on wrong side. (Xerox SPAR # 328230523, EFI Bug # 1-9MHVS)

**Solution:**

Download the enclosed 1-9MHVS.ps to the Fiery.

This update consists of the following file:

File Name	File Size
1-9MHVS.ps	185 KB

**Important Note:**

This patch requires and was tested with composite patch 1-7QU5B pre-installed.

**Installation Instructions:**

1. Download 1-9MHVS.ps file via the Fiery Downloader, Web Downloader or Command WorkStation to the Print queue or Direct Connection.  
Note: Downloading via Command WorkStation, refer to the Job Management Guide, Page 3-7  
Downloading via Fiery Downloader, refer to the Printing Guide, Page 4-4  
Accessing the Web Downloader, refer to the Printing Guide, Page 9-2
2. Wait 60 seconds.
3. Reboot the Fiery server from the Fiery Control Panel.
4. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-9MHVS.