

Patch Installation Instructions

XOG DFE SPAR Team

Product(s):	DocuColor 242/252/260 Integrated Fiery Color Server v2.0	Date:	02/14/2013
Title:	1-1IJ6ZK Installation Instructions	Page:	1 of 1

Purpose

This software patch provides a 2.0 software update in response to a DocuColor 242/252/260 Integrated Fiery Color Server SPAR. Refer to the included customer letter for more information.

In the event of a 2.0 system reinstall this software should be reapplied.

Kit Contents

Qty.	Description
1	Patch Installation Instructions
1	Customer Letter
1	1-1IJ6ZK.ps

Prerequisites

- Previous working knowledge with the DocuColor 242/252/260 Integrated Fiery Color Server.
- The DocuColor 242/252/260 Integrated Fiery Color Server must be at version 2.0 prior to performing this install. This software is supplemental to the 2.0 launch software.
- PRODID
- 1-U8E58
- 1-18SMZM
- 1-1E21N4
- 1-13LK3J
- 1-19AZVM
- 1-1CNL1W
- 1-1H1YIQ
- 1-1FLFQA

2. You must wait at least 60 seconds after importing the patch file before rebooting the system. This will ensure the patch file is completely processed.
3. From Command Workstation, select **Server > Reboot Server**. The Fiery will reboot.
4. Wait until the Fiery has come to idle and print out the configuration page.
5. Verify the **Update Info** section. It should contain the patch number **1-1IJ6ZK**.

NOTE: For those customers that do NOT use EFI Auto-Updates and do NOT use FreeFlow® the following patch configuration is to be considered the minimum required. If at a later time the customer decides to add FreeFlow® or enable EFI Auto-Updates, a complete reload of the Fiery to the above configuration will be required.

- PRODID
- 1-U8E58
- 1-18SMZM
- 1-1E21N4
- 1-1H1YIQ

Installation Instructions

NOTE: The customer or a member of the Xerox Service Team may install this software.

1-1IJ6ZK:

Before upgrading the software, ensure there are no other jobs processing.

1. Import the patch file **1-1IJ6ZK.ps** with Command Workstation to the **Direct** queue.