

April 2013

Dear Xerox XC550/560 Integrated Fiery Color Server customer:

Your XC 550/560 Integrated Fiery Color Server can now be upgraded with the **1.1sp6** software patch.

NOTE: *Your system must be at version 1.1, sp1 sp2, sp3, sp4 and sp 5 prior to installing this software.*

We tested this software patch specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software patch contains fixes for the following SPARs:

SPAR #	Description
1. 026247143	Image enhancement not working correct
2. ESC 1622/1541	Getting an error when doing booklet to a c3 finisher on coated 1
3.	DST values are not updated for all time zone

Other fixes included:

- 1-1HVLNB – **Rip error is observed when printing a file**
- 1-1JE9W3 -**Web applications held job UI buttons disappears after sending a few job to hold .**

NOTE: *Not all child SPARs will be listed in this letter.*

Prerequisites:

1.1sp1

1.1sp2

1.1sp3

1.1sp4

1.1sp5