

# Patch Installation Instructions

XOG DFE SPAR Team

Product(s):	DocuColor 242/252/260 Integrated Fiery Color Server v2.0	Date:	03/19/2013
Title:	1-1J9XON Installation Instructions	Page:	1 of 1

## Purpose

This software patch provides a 2.0 software update in response to a DocuColor 242/252/260 Integrated Fiery Color Server SPAR. Refer to the included customer letter for more information.

In the event of a 2.0 system reinstall this software should be reapplied.

## Kit Contents

Qty.	Description
1	Patch Installation Instructions
1	Customer Letter
1	1-1J9XON.ps

## Prerequisites

- Previous working knowledge with the DocuColor 242/252/260 Integrated Fiery Color Server.
- The DocuColor 242/252/260 Integrated Fiery Color Server must be at version 2.0 prior to performing this install. This software is supplemental to the 2.0 launch software.
- PRODID
- 1-U8E58
- 1-18SMZM
- 1-1E21N4
- 1-13LK3J
- 1-19AZVM
- 1-1CNL1W
- 1-1H1YIQ
- 1-1FLFQA
- 1-1IJ6ZK

## Installation Instructions

**NOTE:** The customer or a member of the Xerox Service Team may install this software.

### 1-1J9XON:

Before upgrading the software, ensure there are no other jobs processing.

1. Import the patch file 1-1J9XON.ps with Command Workstation to the **Direct** queue.

2. You must wait at least 60 seconds after importing the patch file before rebooting the system. This will ensure the patch file is completely processed.
3. From Command Workstation, select **Server > Reboot Server**. The Fiery will reboot.
4. Wait until the Fiery has come to idle and print out the configuration page.
5. Verify the **Update Info** section. It should contain the patch number 1-1J9XON.