

RELEASE NOTES

General information	
Issue ID Number	1-AYCVA
Product Name	All Xerox NT based Fiery's with sp6a installed.
Issue Date	09/15/2003

Files included in this release	
File name	File size
1-AX761.ps	10.2 MB
relnotes.pdf	

Issue description	
Microsoft Security Bulletin MS03-039 / Microsoft Hot-fix Q824146	
Steps to reproduce	
Please see Microsoft's Website for more details: http://support.microsoft.com/default.aspx?scid=kb;en-us;823980	
Resolution type:	Closed - Patch
Resolution	
1-AX761.PS	
Important notes	
<p>This patch resolves the issues outlined in Microsoft's Security Bulletin MS03-039. This patch will install the Q824146 Hot-fix.</p> <p>Pre-requisite for this patch is a Fiery that has sp6a already installed, either by default or through a patch. Please contact your EFI technical services representative to obtain detailed information about the need to install a patch for sp6a.</p> <p>Installation instructions:</p> <ol style="list-style-type: none">1) Download patch 1-AX671.ps using CWS or Downloader to Direct connection of Fiery.2) After Fiery returns to "Idle", wait 60 seconds3) Reboot Print Controller through the "Reboot System" option in LCD Shut Down menu. Note: do not reboot from CWS.4) Fiery will boot up and then will reboot itself.5) Let Fiery come to idle.6) Print the configuration page and make sure the correct information appears (Update Info section should appear with 1-AX671).7) Installation is complete	

