

## ***Microsoft Security Bulletin MS03-026 & MS03-039 X40 1.0***

### **Problems Addressed:**

Addresses the Microsoft Security Bulletin MS03-026 and MS03-039.

### **Solution:**

Download the enclosed 1-ANKZ9 & 1-AX671.ps to the Fiery individually.  
This update consists of the following file:

<b>File Name</b>	<b>File Size</b>	<b>Notes</b>
1-ANKZ9.ps	407 MB	Installs Service Pack 6a
1-AX671.ps	10.2 MB	Installs MS03-026 and MS03-039 fixes

### **Important Note:**

The Fiery X40 requires the Service Pack 6a installer 1-ANKZ9 to be installed prior to installation of the hotfix patch 1-AX671.

### **1-ANKZ9 Installation Instructions:**

1. Download 1-ANKZ9.ps file via the Fiery Downloader or Web Downloader to the Direct queue or if using the import function of CWS 4.x, import to the Direct queue.
2. Wait 60 seconds.
3. Reboot the Fiery server from the Fiery Control Panel.
4. After boot process finishes, LCD will display a message that SP6a is being installed.
5. After SP6a installation is finished, the system will boot to Idle.
6. Reboot the Fiery server again from the Fiery Control Panel.
7. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-ANKZ9.

Please note: For Fiery Systems with FACI – the NT Administrator now has a password: “Fiery.1”

### **1-AX671 Installation Instructions:**

1. Download 1-AX671.ps file via the Fiery Downloader or Web Downloader to the Direct queue or if using the import function of CWS 4.x, import to the Direct queue.
2. Wait 60 seconds.
3. Reboot the Fiery server from the Fiery Control Panel.
4. Fiery server will boot up and then reboot itself.
5. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-AX671.

PK – 9/19/03