

July 2008

Dear Xerox EX260 customer:

Your EX260 system can now be upgraded with the **1-XMDF0** software kit.**NOTE:** This patch may be installed by the customer following the enclosed *Installation Instructions*.**NOTE:** Your system must be at version EX260 v2.0 with patch 1-VTO62 prior to installing this software.**NOTE:** This patch supersedes the following patches: 1-W3DS2, 1-VBYZ2, 1-XMDEU, 1-XDJ75, 1-X4RRL, 1-X6BXX, and 1-XHT21.

We tested this updated software release specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software kit contains fixes for the following SPARs:

| SPAR Release | | Patch ID # | Description |
|-------------------------|----|------------|--|
| SPAR kit version | | | |
| 1-XMDF0 | 1. | 1-W3DS2 | Composite patch for 1-TW68H; 1-V1KA5; 1-VH8V5; 1-TW68O; 1-TTL3P; 1-UWKF6; 1-W1Z8P. |
| | 2. | 1-VBYZ2 | Configuration pages are printed without the System Update Log page with EX260 loaded with Dutch language. |
| | 3. | 1-XMDEU | Printing does not commence after the correct paper is loaded into Tray 5 when a paper size mismatch is detected. |
| | 4. | 1-XDJ75 | Landscape Jobs from Mac InDesign CS3 starting with the 2nd page prints images rotated 90 degrees. |
| | 5. | 1-X4RRL | This patch addresses a side effect introduced with patch 1-XB6XX. |
| | 6. | 1-X6BXX | Composite patch for 1-TVM69; 1-WT7BX; 1-X3SFD. |
| | 7. | 1-XHT21 | Composite patch for 1-XBW3E; 1-X3RTJ; 1-X1I9K. |

NOTE: Not all child SPARs will be listed in this letter.