

## Scanning Templates CXP3535

### Problems Addressed:

Scanning templates are not updated when the user switches from G3535 to CXP3535 to the same DC3535 copier/printer.

### Solution:

Use the enclosed utility.

This update consists of the following file:

File Name	File Size
reset_scan_params.bat	473 B
snmputil.exe	66.1 KB

### Installation Instructions:

1. Exit the Spire CXP3535 application.
2. Extract the zip. This will automatically create a folder called **ResetScanParams**.
3. Copy **ResetScanParams** folder into the C:\ drive on the Spire CXP3535 server.
4. Connect the CXP3535 to the DC3535.
5. In CXP3535, go to **C:\ResetScanParams** and double click the file *reset\_scan\_params.bat* file.
6. After performing above steps, you should be able to use the Scan from the DC3535 to CXP3535 successfully.