

Release Note

General information	
Issue ID Number	1-DCY0M
Product Name	Fiery X5 for EX1010 PCL5 version 1.2
Issue Date	4 June, 2004

Files included in this release	
File name	File size
1-DCY0M.ps	510 KB

Issue description	
SPAR 906747839 PCL Job will not pull from Tray 1 when Tray 1 is selected in driver.	

Steps to reproduce	
n/a	

Resolution type:	Closed - Patch
------------------	----------------

--

Resolution

1-DCY0M.ps

Important notes

Installation Steps:

1. Download/Import the patch file “1-DCY0M.ps” with either Fiery Downloader or Command Workstation to the “Direct” queue.
2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.
3. The system must be rebooted twice for the patch to be effective.
4. Please select “Shut Down” and then “Reboot System” on the Fiery LCD. When the Fiery has come to “Idle”, repeat the steps to reboot the system.
5. Please wait until the Fiery has come to idle after the second reboot to print out the configuration page.

Verify the **Update Info** section. It should contain the patch number “1-DCY0M”.

Known Issues
No known issues