

Release Note

| General information | |
|---------------------|--------------------------------------|
| Issue ID Number | 1-CXV45 |
| Product Name | Fiery Z5 for EX1010 PCL5 version 1.0 |
| Issue Date | 4 June, 2004 |

| Files included in this release | |
|--------------------------------|-----------|
| File name | File size |
| 1-CXV45.ps | 510 KB |
| | |

| Issue description | |
|---|----------------|
| SPAR 381197627 Tray selection is not honored with PCL driver. | |
| Steps to reproduce | |
| n/a | |
| Resolution type: | Closed - Patch |
| | |
| Resolution | |
| 1-CXV45.ps | |

| Important notes | |
|---|--|
| Installation Steps: <ol style="list-style-type: none">1. Download/Import the patch file “1-CXV45.ps” with either Fiery Downloader or Command Workstation to the “Direct” queue.2. You must wait at least 60 seconds after the patch file downloaded/imported before rebooting the system. This will ensure the patch file is completely processed.3. The system must be rebooted twice for the patch to be effective.4. Please select “Shut Down” and then “Reboot System” on the Fiery LCD. When the Fiery has come to “Idle”, repeat the steps to reboot the system.5. Please wait until the Fiery has come to idle after the second reboot to print out the configuration page. | |
| Verify the Update Info section. It should contain the patch number “1-CXV45”. | |

| Known Issues |
|-----------------|
| No known issues |