# Kit Installation Instructions

PSG SPAR Team

| Product(s): DocuColor 250/240 bustled Fiery color server | Date: 07/02/08 |
|---|---|
| Title: Patch 1-XVE1A Installation instructions | Page: 1 of 1 |

## Purpose

This software kit provides a version 1.2 software update in response to a DocuColor 250/240 bustled Fiery color server SPAR. Refer to the included customer letter for more information.

In the event of a version 1.2 system reinstall this software should be reapplied.

## Kit Contents

| Qty. | Description |
|---|---|
| 1 | Kit Installation Instructions |
| 1 | Customer Letter |
| 1 | Patch 1-XVE1A.ps |

## Prerequisites

- Previous working knowledge with the DocuColor 250/240 bustled Fiery color server.

- The DocuColor 250/240 bustled Fiery color server must be at version 1.2 prior to performing this install. This software is supplemental to the version 1.2 launch software.

## Installation Instructions

*Note: This patch is Exclusive which means it must be installed independently and the server rebooted/restarted once. After which, other patches can be applied to the server.*

__ 1. Import the patch file **1-XVE1A.ps** with Command Workstation to the **Direct** queue.

__ 2. You must wait at least 60 seconds after importing the patch file before rebooting the system. This will ensure the patch file is completely processed.

__ 3. From Command Workstation, select **Server > Reboot Server**. The Fiery will reboot.

__ 4. Wait until the Fiery has come to idle and print out the configuration page.

__ 5. Verify the **System Update Log**. It should contain the patch number **1-XVE1A**.