Xerox Wide Format 6705 System Controller SW Release Note V.1.00.19.00

Created by	C-Cont Confimed by	P-Cont(PS) Confirmed by	P-Cont Confirmed by	UI Confirmed by	Client Confirmed by	Apprived by
'13.6.13 FX CTPF2 N.Satoh S.Hamano	'13.6.10 FXAT MSW S.Oizumi	'13.6.10 FXAT CTS3 T.Kubodera	'13.6.10 FX CTPF2 Ka.Suzuki	'13.6.10 FX CTPF2 N.Honma	'13.6.10 FX CTPF2 N.Kaneko	'13.6.13 FX CTPF2 T.Yamada

<Overview>

Release note for V1.00.19.00.
This note includes changes from V1.00.09.00 to V1.00.19.00.

<SW version information>

	File Name	Version	Issue Date	Registration name for CVS TAG
Controller SW	cp-cont	1.00.19.00	2013/06/13	Bonito_Release_1.0.19.00-20130613
IIT USER	05_User_lit_s.dat	1.00.03	2012/07/06	
IIT IPS	04_Ips_s.dat	1.00.00	2012/03/30	
IOT	Bonito_Iot_all_Ver1102.mot	1.1.02	2013/04/04	

<Addition/ modification: Others>

SC No.	Function	Note
	Added 9 languages for MN market	UI / C-Cont / P-Cont
	Multi-language support (converted the text cords according to the text code conversion parameters)	P-Cont
	Text: Updated MN 9 language messages (DMO released on 6/5 and FX modified)	UI

<Fixed/ Improved Problems (changes from V1.00.09.00)>

Proweb	AR No.	Problem	Note
	17533	Problem of English and Chinese versions, which was that the print result of the sample copying and the message displayed on UI were not identical, was fixed (changed the messages of the sample copying).	C-Cont
	17572	Mailbox viewer and DocuWorks do not indicate the size when machine scans 21x30 size and 10.5x15 size documents.	C-Cont
	17469	When an operator selects a roll on the screen, then opens and closes the RFC door, screen displays the message to replenish the selected media despite the fact that plenty of the media is loaded.	C-Cont
	17473	Paper map problem of Arch30 series	P-Cont
76250 83753	16702 17481	E0901error occurred and printed the stamp only (rest of the image were not printed).	P-Cont
		Network reference problem. Controller cannot read correctly if the character '-' is written at the head of the name.	P-Cont
	17555 17570	Error [016-380] occurred by Bulk Deletion of data	P-Cont
	17602 17603	Problem, which occurred when a space and 9 or more of consecutive '-' were included in the shared name, the name was not displayed in the Network reference, has been fixed.	P-Cont
	17576	Machine do not print the sample copying when the language is switched from English to Chinese.	UI / C-Cont

＜**Notes and restrictions**＞

1. In either of the following case, the Computer Name / Domain Name / Workgroup Name on the destination list on the "Browse" screen may be garbled or may not be shown.

    - The character(s) other than the Uppercase alphabets ("A" through "Z"), the lowercase alphabets ("a" through "z"), the numbers ("0" through "9"), and minus ("-") is(are) used for Domain Name /Workgroup Name of the host PC.

2. When the Domain Name / Workgroup Name exceeds 14 bytes, the Computer Name / Domain Name /Workgroup Name of the host PC will not be shown on the destination list on the "Browse" screen.

3. The logo does not appear on the screens 2/7 to 4/7 when the machine starts up for the first time after loaded with the fix version (V1.00.09.00 or later), but it will appear from the next starting up.

4. The sysObjectID of the controller is different between FX market products (Japan/ AP/GCO) and DMO market products.
    Therefore, the following clients that use MIB to detect devices may not work if the setting appropriate for each market is not used.

    - Device detection with NetworkScannerUtility3