DocuColor 240/250 Integrated Fiery Color Server

January 2009

Dear Xerox DocuColor 240/250 Integrated Fiery Color Server customer:

Your DocuColor 240/250 Integrated Fiery Color Server system can now be upgraded with the 1-116UK9 software kit.

NOTE: This patch may be installed by the customer following the enclosed Installation Instructions.

NOTE: Your system must be at version 1.2 prior to installing this software.

We tested this updated software release specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software kit contains fixes for the following SPARs:

SPAR Release	SPAR #	Description
SPAR kit version		
	1. 404916429	Importing an archived job hangs in a processing state.
	2. 548635678	Output of archived images are corrupted.
	3. 427082149	Printing a PDF with a barcode from Acrobat 8 Professional's PS driver outputs a corrupted barcode image.
	4. 213016802	Files printed from Corel X4 outputs black box prints over the image.
	5. 973182359	CorelDraw X4 file's output with missing images.
	6. 904029027	Output image is distorted.

NOTE: Not all child SPARs will be listed in this letter.