

Print-quality modes

Mode	Maximum speed *	Description
Fast Color	10 ppm Paper 5 ppm Transparency	<ul style="list-style-type: none">■ Fastest full-color output.■ Useful for many images and previewing work.■ Rapidly produces good quality transparencies and peer-level documents.■ Useful for rush jobs and situations where having the most saturated colors is not necessary.
Standard	6 ppm Paper 3 ppm Transparency	<ul style="list-style-type: none">■ General-purpose mode for full-color printing.■ Produces crisp, bright prints suitable for most office use.■ Recommended for high-quality transparencies.■ Produces vibrant, saturated prints with smooth color transitions.
Enhanced†	3 ppm Paper	<ul style="list-style-type: none">■ Balance of high quality and fast speed.■ Smoothest and brightest large-area fills.■ Useful for printing paper copies of overhead presentations.
High Resolution/ Photo†	2 ppm Paper	<ul style="list-style-type: none">■ Requires the Plus Feature set.■ Highest-quality color prints, 1200 x 600 dpi resolution.■ Near-photographic detail.

* Approximate number of pages per minute.

† Transparencies will be printed in Standard mode.