

***Collating
EX12 2.0*****Problems Addressed:**

Collate option fails when job is saved after previewed from a held state. (EFI Bug # 1-76RJI)

Solution:

Download the enclosed 1-76RJI.ps to the Fiery.

This update consists of the following file:

File Name	File Size
1-76RJI.ps	815 KB
CWS 4.1.017 folder	48.8 MB

Important Note:

This patch requires and was tested with composite patch 1-7QU5B pre-installed.

Installation Instructions:

1. Download 1-76RJI.ps file via the Fiery Downloader or Web Downloader to the Print queue or if using the import function of CWS 4.x, import to the Hold queue, then print.
2. In Command Workstation/Spooler (web), verify that 1-76RJI.ps is in the printed queue.
3. Wait 60 seconds.
4. Reboot the Fiery server from the Fiery Control Panel.
5. After the server has restarted, please wait until it goes to idle and print a Configuration Page to verify that the file has been received. The Update Information should contain the patch number 1-76RJI.ps.

Command WorkStation Installation Instructions:

Note: Remove any previous versions of Command WorkStation before installing.

Removal Procedure:

1. Go into Start/ Settings/ Control Panel.
2. Select Add/Remove Program. Scroll down and select Command WorkStation 4.x.
3. Click on the Add/Remove button.
4. Follow the on-screen instructions.

Install Procedure:

1. Open *CWS 4.1.017* folder
2. Open *CStation 4* folder.
3. Double click on *Setup.exe* file.
4. Follow the on-screen instructions.
5. At the end of the installation it will prompt to reboot your computer. Please reboot your computer.
6. Installation is complete. Go to Start/ Program/ Fiery to launch the updated version of CWS.