

Patch Installation Instructions

XOG DFE SPAR Team

Product(s):	DocuColor 242/252/260 Integrated Fiery Color Server v2.0	Date:	12/19/2011
Title:	1-1CNL1W Installation Instructions	Page:	1 of 1

Purpose

This software patch provides a 2.0 software update in response to a DocuColor 242/252/260 Integrated Fiery Color Server SPAR. Refer to the included customer letter for more information.

In the event of a 2.0 system reinstall this software should be reapplied.

Kit Contents

Qty.	Description
1	Patch Installation Instructions
1	Customer Letter
1	1-1CNL1W.ps

Prerequisites

- Previous working knowledge with the DocuColor 242/252/260 Integrated Fiery Color Server.
- The DocuColor 242/252/260 Integrated Fiery Color Server must be at version 2.0 prior to performing this install. This software is supplemental to the 2.0 launch software.
- PRODID
- 1-13LK3J

Installation Instructions

NOTE: The customer or a member of the Xerox Service Team may install this software.

1-1CNL1W:

Before upgrading the software, ensure there are no other jobs processing.

1. Import the patch file **1-1CNL1W.ps** with Command Workstation to the **Direct** queue.
2. You must wait at least 2 minutes after importing the patch file before rebooting the system. This will ensure the patch file is completely processed.
3. From Command Workstation, select **Server > Reboot Server**. The Fiery will reboot.
4. Wait until the Fiery has come to idle and print out the configuration page.
5. Verify the **Update Info** section. It should contain the patch number **1-1CNL1W**.