

Kit Installation Instructions

XOG SPAR Team

Product(s):	EX 550/560	Date:	10/24/2013
Title:	1.1SP8 Installation Instructions	Page:	1 of 1

Purpose

This software kit provides an EX550/560 software update in response to an EX550/560 SPAR. Refer to the included customer letter for more information.

In the event of an EX550/560 system reinstall this software patch should be reapplied.

Kit Contents

Qty.	Description
1	Kit Installation Instructions
1	Customer Letter
1	EX550_560_SP8.exe

Prerequisites

- Previous working knowledge with the EX550/560
- 1.1SP1
- 1.1SP2
- 1.1 SP3
- 1.1SP4
- 1.1SP5
- 1.1SP6
- 1.1SP7

Installation Instructions

NOTE: This software may be installed by the customer.

Install the EX550/560 SP8.exe patch:

- ___ 1. Install the EX550_560_SP8 patch
 - ___ a. Double click on EX550_560_SP8.exe file
 - ___ b. At the Fiery Patch Download window, click [Next]
 - ___ c. At the License Agreement window, click [Accept]
 - ___ d. At the Fiery Logon window, type the Fiery administrator login password in the Password field

NOTE: Do NOT change the User field; that value must be admin.
 - ___ e. In the Hostname field, type in the IP address or hostname of the EX550/560 and select [Connect]

- ___ f. At the Server Information window, select [Download]. The patch will be downloaded and installed
- ___ g. At the Processing window, select [Next], wait for approximately one (1) minute
- ___ h. On the final window, select [Reboot], then select [Finish]

NOTE: The patch will not be installed until the EX550-560 is rebooted.

- ___ 2. Verify that the patch is installed and wrap-up
 - ___ a. Once the Fiery status says "Idle," select [Server: Print Pages] from the CWS menu and print a configuration page.
 - ___ b. On the "System Update Log" sheet of the configuration pages, ensure that the patch SP8 is listed

NOTE: When executing SP8.exe, if you choose **Restart later** when prompted by the Fiery Patch Downloader, please make sure you manually reboot the server for changes to take effect.

NOTE: There is a uninstaller for SP8. Just double click on the uninstall_sp.exe and follow the instruction to remove SP8.