

Kit Installation Instructions

XOG SPAR Team

Product(s):	CX260_v2.0_SP1 for DocuColor 242/252/260	Date:	05/13/08
Title:	Patch_Out_of_place Installation instructions	Page:	1 of 1
Instruction #:	Kit Part #:		

Purpose

This software kit provides a CX260_v2.0_SP1 software update in response to a CX260 SPAR. Refer to the included customer letter for more information.

In the event of a CX260 system reinstall this software should be reapplied.

Kit Contents

Qty.	Description
1	Kit Installation Instructions
1	Customer Letter
1	Patch_Out_of_place.zip

Prerequisites

- Previous working knowledge with CX260_v2.0_SP1.
- The CX260 must be at version **2.0_SP1** prior to performing this install. **ATS Firmware 121018Patch 22-Nov-2007** must also be loaded prior to performing this install. This software is supplemental to the version 2.0_SP1 launch software.

Installation Instructions

NOTE: This software may be installed by the customer.

- ___ 1. Exit the Spire application.
- ___ 2. Extract **Patch_Out_of_place.zip** to the CX260 Windows desktop.
- ___ 3. Open the **Patch_Out_of_place** folder.
- ___ 4. Double-click on the **Install.exe** file. Follow the onscreen instructions.
- ___ 5. Launch the Spire application and open **Help > About** to confirm that the patch was installed successfully. The patch will be listed under **Updates** as **Out_of_place_fix**.

Uninstallation Instructions

- ___ 1. Exit the Spire application.
- ___ 2. Extract **Patch_Out_of_place.zip** to the CX260 Windows desktop.
- ___ 3. Open the **Patch_Out_of_place** folder.
- ___ 4. Double-click on the **Uninstall.exe** file. Follow the onscreen instructions.
- ___ 5. Launch the Spire application and open **Help > About** to confirm that the patch was uninstalled successfully. The patch will not be listed under **Updates**.