

XC 550/560 Integrated Fiery Color Server



Xerox Corporation
800 Phillips Road
Webster, NY 14580

January 2012

Dear Xerox XC550/560 Integrated Fiery Color Server customer:

Your XC 550/560 Integrated Fiery Color Server can now be upgraded with the **1-1E1G7Z** software patch.

NOTE: *Your system must be at version 1.1 prior to installing this software.*

We tested this software patch specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software patch contains fixes for the following SPARs:

SPAR #	Description
1.	Mac OS 10.7 updated driver for 2 byte font support for Russian and simplified Chinese

NOTE: *Not all child SPARs will be listed in this letter.*

Prerequisites: