

Patch Installation Instructions

XOG DFE SPAR Team

Product(s):	XC 550/560 Integrated Fiery Color Server	Date:	1/2012
Title:	1-1E1G7Z Installation Instructions	Page:	1 of 1

Purpose

This software patch provides a 1.1 software update in response to a XC550/560 Integrated Fiery Color Server SPAR. Refer to the included customer letter for more information.

In the event of a system reinstall this software should be reapplied.

Kit Contents

Qty.	Description
1	Patch Installation Instructions
1	Customer Letter
1	1-1E1G7Z.zip

Prerequisites

- Previous working knowledge with the XC 550/560 Integrated Fiery Color Server.
- The XC 550/560 Integrated Fiery Color Server must be at version 1.1 prior to performing this install. This software is supplemental to the 1.1 launch software.

Installation Instructions

NOTE: The customer or a member of the Xerox Service Team may install this software.

1-1E1G7Z.zip:

Before upgrading the software, ensure there are no other jobs processing.

1. Please use the Fiery Printer Delete Utility provided on the User CD to uninstall the previously installed fiery driver
2. Please reboot the client system after the driver has been uninstalled
3. Double Click on the zip on file and unzip it.
4. Then run the DMG installer and install the new mac driver
5. Install the printer using the new driver installed.