

Release Note

General information	
Issue ID Number	1-L9NX3
Product Name	Fiery Network Controller for DC3535 v. 1.1
Issue Date	January 27, 2006

Files included in this release	
File name	File size
1-L9NX3.ps	152 KB
1-L9NX3_relnotes.doc	

Issue(s) addressed with this release

Can not choose Page Size in CWS when connecting to DC3535

Steps to reproduce

App: Command Workstation 4.1.0.21

- 1) Log into DC3535 via CWS
- 2) From the Printed Jobs screen, right click on column names to add more settings
- 3) From the list, Page Size is not available
- 4) Log into another Fiery (XP12 SP2 for instance)
- 5) From the Printed Jobs screen, right click on column names to add more settings
- 6) From the list, select Page Size

Result: DC3535 does not allow the user to add Page Size attribute in CWS.

Prerequisite(s)

1-GUITT is recommended.

Installation instructions

1. Download/Import the patch file “1-L9NX3.ps” with Command Workstation to the “Direct” queue.
2. You must wait at least 60 seconds after the patch file has downloaded/imported before rebooting the system. This will ensure the patch file is completely processed. A page will be printed confirming that the patch has been downloaded successfully.
3. The system must now be power-cycled for the patch to take effect. Power the system down using the power switch on the front of the copier, wait for it to shut off completely, then turn it back on.
4. Please wait until the Fiery has come to idle after the reboot to print out the configuration page.

Verify the Updated Information section of the configuration page. It should contain the patch number “1-L9NX3”.

Known Issues

None