

Release Note

General information	
Issue ID Number	1-I96ZJ
Product Name	Fiery Network Controller for DC3535 v. 1.1
Issue Date	March 21, 2005

Files included in this release	
File name	File size
1-I96ZJ.ps	24 Kilobytes
1-I96ZJ_relnotes.doc	44 Kilobytes

Issue(s) addressed with this release

Customer wants to disable the Hold queue

Steps to reproduce

After 1-GUITT, hold queue can not be disabled. Want to change the behavior so print queue cannot be disabled, but Hold and Direct queues can be.

Installation instructions

(Please use “numbering” to write the install instructions)

1. Download/Import the patch file “1-I96ZJ.ps” with Command Workstation to the “Direct” queue.
2. Allow the file to finish processing. A patch page will be printed confirming that the patch has been downloaded successfully.
3. The system must be power-cycled for the patch to take effect. Power down the system using the power switch on the front of the copier, wait for it to shut off completely, then turn it back on.
4. Please wait until the Fiery has come to idle after power-cycling to print out the configuration page.

Verify the **Update Info** section. It should contain the patch number “1-I96ZJ”.

Prerequisite(s)

None

Known Issues

None