

# EFI Fiery™ for the Xerox® EX-c C8000 Print Server

PostScript patch release note



## Overview

This checklist will help you prepare for the installation of **SP1\_FIT101686556.ps**.

### General Information

○ Current Version	1.0
○ Defect ID	FIT101686556
○ Release Date	01-May-2017
○ Files included	Xerox_AltaLink_C8030___C8035___C8045___C8055___C8070_SP1.ps
○ File size	1,484,483 bytes
○ Files included	uninstall_sp.exe
○ File size	31,262 bytes

## Issue(s) addressed with this release

- 1) FIT000248995 : Unable to take audit log after configuring with EFI
- 2) FIT101595553 : Unable to login as admin in Xerox Altalink C8000 Series engine webpage (CWIS)
- 3) FIT101592885 : Unexpected lines of error code observed while trying to save any change in CWIS properties.
- 4) FIT101638607 : Job stuck in printing while Print Quality: Enhance is used

## IMPORTANT

### Before installing SP1.ps

1. Known issues listed below, read before installing  
**Xerox\_AltaLink\_C8030\_\_\_C8035\_\_\_C8045\_\_\_C8055\_\_\_C8070\_SP1.ps** patch:
  - None.
2. The following prerequisite(s) must be installed in the order specified before applying the  
**Xerox\_AltaLink\_C8030\_\_\_C8035\_\_\_C8045\_\_\_C8055\_\_\_C8070\_SP1.ps** patch:
  - 1.0.
3. Do NOT install any of the following patch(es) after installing the  
**Xerox\_AltaLink\_C8030\_\_\_C8035\_\_\_C8045\_\_\_C8055\_\_\_C8070\_SP1.ps** patch. If you must install any of the patch(es) below, do so before installing the  
**Xerox\_AltaLink\_C8030\_\_\_C8035\_\_\_C8045\_\_\_C8055\_\_\_C8070\_SP1.ps** patch:
  - None.

### Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

1. Functionality to execute copy-protected programs
2. Functionality to access to digital contents stored on copy-protected read-only media
3. Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
4. Functionality for copying control of copyright protected audio/video data
5. Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits

# EFI Fiery™ for the Xerox® EX-c C8000 Print Server

## PostScript patch release note



4. This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.

### Patch installation instructions

1. Make sure that the Fiery controller has reached Idle.
2. Import the patch file  
**Xerox\_AltaLink\_C8030\_\_\_C8035\_\_\_C8045\_\_\_C8055\_\_\_C8070\_SP1.ps** using Command WorkStation to the Direct connection.
3. You must wait until the file finishes processing and Service Pack instruction page is printed and Command WorkStation or the LCD show Idle.
4. From Command WorkStation, choose Server, Reboot Server, or from the Fiery LCD, select Shut down, Reboot System.
5. Wait until the Fiery controller reaches Idle and print the configuration page.
6. Verify that the Update Info section contains the patch number **SP1\_FIT101686556**.

### How to Uninstall SP1\_FIT101686556 patch:

If at any reason, the **SP1\_FIT101686556** needs to be uninstalled, please follow below instructions:

### Before installing uninstall\_sp.exe

1. This patch is exclusive, it must be installed by itself, and the server must be rebooted or restarted once. After that, other patches can be applied to the server.
2. If any prerequisites listed below, they must be installed in the order specified before applying the **uninstall\_sp.exe** patch:
  - **SP1\_FIT101686556**
3. If any known issues listed below, read before installing **uninstall\_sp.ps** patch:
  - This patch will only uninstall **SP1\_FIT101686556**. If there are any patches installed after **SP1\_FIT101686556**, the uninstaller patch will not uninstall **SP1\_FIT101686556**.

### Patch installation instructions

1. Make sure that the Fiery printer controller reaches Idle.
2. Import the patch file **uninstall\_sp.ps** using Command WorkStation to the Direct connection.

#### Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

1. Functionality to execute copy-protected programs
2. Functionality to access to digital contents stored on copy-protected read-only media
3. Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
4. Functionality for copying control of copyright protected audio/video data
5. Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits

# EFI Fiery™ for the Xerox® EX-c C8000 Print Server

PostScript patch release note



3. You must wait until the file finishes processing and Command WorkStation or the LCD show Idle.
4. From Command WorkStation, choose Server, Reboot Server, or from the Fiery LCD, select Shut down, Reboot System.
5. Wait until the Fiery controller reaches Idle and print the configuration page.
6. Verify that the Update Info section does not contain the patch number **SP1\_FIT101686556**.

## Disclaimer

This hardware, software/patches, or technology may contain cryptographic functions as defined in Article 8 (ix) (h) because the cryptographic capability is not user-accessible, and are designed to have only one or more of the following cryptographic functionality(ies):

1. Functionality to execute copy-protected programs
2. Functionality to access to digital contents stored on copy-protected read-only media
3. Functionality to access to encrypted and memorized digital contents on a medium that will be sold to the public with the same content
4. Functionality for copying control of copyright protected audio/video data
5. Functionality to encrypt and/or decrypt to protect libraries, design attributes, or associated data for the design of semiconductor devices or integrated circuits