

DigiPath Customer Bulletin

Configuration : DigiPath

Release : DigiPath 3.0.0.20

FreeFlow Number : Bulletin 96

Distribution Date : 2/05

Expiration : Never

Title : Announcing DigiPath Patch Software Version 3.0.0.20

ANNOUNCEMENT

A new DigiPath baseline patch software version 3.0.0.20 (Kit # 301K14420) has been released for mass distribution as the new baseline for DigiPath software. This patch should be installed on all DigiPath 3.0 software systems effective March 1, 2005. The software will be included within the distribution to the field as part of the FreeFlow 3.0 kit. All software support channels will be based on the assumption that all systems have been upgraded to this version.

All DigiPath patches are cumulative which means that all new patches also contain all of the previous patches within them. A listing of all SPARS fixed for each version of patch software is listed below.

NOTE: This is the final Software patch for DigiPath 3.0 and this will be available for ordering out of MAPS on March 1st, 2005.

DigiPath Patch 3.0.0.20

This software release has been made available to include the necessary software changes to enable the migration activity from 3.0.0.20 to the latest FreeFlow software.

SPAR support for the DigiPath 3.0 release has been discontinued. Effective September 1, 2004. SPARs will no longer be received against DigiPath 3.0.

The current release 3.0.0.20 still has Customer and Service support by calling the Customer or Technical Support Hotlines and will be the final release of DigiPath 3.0 software.

The current releases accepting SPARs are DigiPath 4.1 and FreeFlow™ 2.0.

If the customer is interested in receiving additional information on upgrading their existing system to the latest FreeFlow platform, they should contact their Sales Representative or Analyst for presales support.

DigiPath 3.0.0.20 includes all fixes provided in 3.0.0.17 through 3.0.0.19 as well as correcting the following problems,

- Can not Uninstall DigiPath 3.0.0.16 with 3.0 license string
- Deskew not working properly
- Deskew breaks up solid lines

DigiPath 3.0.0.19 Patch

The following fix, previously reported with DigiPath 3.0.0.19, are also included in DigiPath SPAR patch 3.0.0.20:

- File are duplicating in Document Library

DigiPath 3.0.0.18 Patch

The following fixes, previously reported with DigiPath 3.0.0.18 are also included in DigiPath SPAR patch 3.0.0.20:

- Views last page of job after page is deleted
- An image quality adjustment problem
- Images are shifting after a crop has been applied
- Unable to cancel a rescan request
- High background when scanning

DigiPath 3.0.0.17 Patch

The following fixes, previously reported with DigiPath 3.0.0.17, are also included in DigiPath SPAR patch 3.0.0.20:

- Cut and paste operation leaves a line on right hand side of image
 - An error in the job ticket when sending a job from production print to DocuSP
- Note: The DocuSP software will need to be at 3.74.18 or higher**
- Staple problem with subset finishing in A3 format with the DP90 printer
 - An RDO-file corrupted error when saving a RDO from DigiPath1.2 to 3.x

EXPIRATION:

FreeFlow 3.0