



Zones are not a requirement for the Fiery but if you know they exist and the Fiery does not see them verify that the Fiery is connected to the network prior to booting up and it should locate any zones available, also verify correct network speed is selected, zones are generated from the novell server - make sure it is up and running.

- ☑ Verify through Ntwork properties that appletalk is bound to the NIC on the bindings tab, if not, reloading software is required
- ☑ On the Mac check to see that Appletalk connection is via ethernet and appletalk is active
- ☑ If the webspooler tries to dial a connection go to remote access in control panel and under options on the protocol tab deselect connect automatically
- Printer lib errors can be avoided by removing the laserwriter printerlib and placing it on the desktop prior to installing the adobe driver, if the printer lib has been overwritten the file can be copied from another mac or a software reload must be done
- ☑ Try disabling the open transport SNMP extension
- This printer requires the AdobePS driver verify this and the ppd







Troubleshooting Fiery NT Environment




Novell Server

What has the customer done to modify the NT?

The only way back for most problems is to restore the OS.

To do this:
(Reboot
holding down
the 4th button
on the right
and choose
restore from
the menu that
comes up.)



Docucolor 2000



Symptoms |

- System has become unstable
- network connections are lost for no reason
- can not read Mac formatted disks


Troubleshoot


IBM Compatible


IBM Compatible

- If Tweak UI has no effect or network bindings to IP and or Apple talk have been lost system software must be restored (a restore only brings back the NT operating system - all other software is loaded from disk)
- The Fiery has a utility called Mac Drive 98 accessed in the NT control panel - ensure that it has not been disabled if you want to read Mac formated disks












Can't connect to Fiery via Windows Printing / SMB






Fiery Advanced Controller Interface

& ACITS don't work with this DFE.

Don't Forget about Hardware!! cables can go bad or be disconnected.



Symptoms

- ☑ Can't see the Fiery in the network neighborhood
- □ can't print

IBM Compatible

- ☑ printer is off-line error message at client PC
- Network errors





🚺 Trust relationship error or prompt for password usually means that the fiery has not been added to the domain or to the DNS server under the windows printing server name network administrator should know how to do this)

- ☑ IP must be enabled on the Fiery
- Verify server name and workgroup/domain name are correct (for windows95 limit server) name to 8 characters)
- Remember the Fiery is limited to 10 simultaneous SMB connections because it is an NT. workstation
- Does the PC have IP/Client for Microsoft Windows/File and print sharing enabled and configured properly?
- ☑ Is the fiery visible in the Network Neighborhood if NO do a find for computer by windows. server name, double click on the printer, it should prompt you for install of the driver




🔀 On small networks - one or two pc's with no gateway use class A IP address, ie. 10.0.0.1 (large networks must supply their own IP structure)






Print Jobs don't leave the NT server







Symptoms



- Nothing is printing
- ☑ Print jobs are still visible at workstaion
- I can print a test page but nothing from my PC
- I can see the fiery in my network neighborhood

Troubleshoot

- ☑ Can the fiery print a test or config page? no= clear server
- ☑ Can you ping the Fiery from the NT Server?
- ☑ Ping doesn't work try to ping another device on the network
- Can ping other devices? Try Tracert command to ip address (this will show how far the packet is going)
- ☑ Check cabling/hub at point where packet dies
- ■ any errors?
- Security errors? is fiery added to domain? should be added by windows server name
- ☑ Is the LPR port setup correctly?
- Is the correct driver being used?(check device settings tab of printer properties click on PS at top of window and then about driver button below) make sure driver corresponds with NT service pack

