

# Product Enhancement Document for WorkCentre 3335/3345 Firmware 60.006.06.000

Release Date: January 13, 2020

dc20rn3921

## Software Release Details

Component	Version
System	60.006.06.000
MCB	V2.50.06.07
Engine (IOT)	V0.00.39_V1.00
Network	4.00.50.81
Link to Software	<a href="#">WC3335/WC3345</a>

### I. Fixes/Features new in this release

- This release reduces some of the factors that causes pits on the drum surface, thus improving the life of the drum.

### II. Installation Notes

Install instructions are included in the zip file containing firmware. Unzip and download before attempting to install the firmware