

Software Version 13.0.7
August 2009



FreeFlow[®] Accxes[®] HP-GL/2 Printer Driver Customer Release Notes



Xerox® Corporation 2009. All rights reserved. Xerox®, the sphere of connectivity design, Xerox Wide Format 6279, 6204, 6030, 6050, 6050A, 510, 721, 8825, 8830, 8850, Xerox Wide Format Scan System, FreeFlow® Accxes®, and acronyms, are trademarks of Xerox Corporation in the United States and/or other countries.

Table of Contents

Release Content	1
New or Changed in this Release.....	2
SPARs fixed in this Release	2
Known Issues	3
Changes to Enable Advanced Printing Feature Checkbox are Propagated between Clients on Remote Printers.....	3
Job is Spread Across Multiple Pages	3
Settings on one Driver Propagated to all Printer Drivers	3
Driver Settings not Saved after Printing from AutoDesk Design Review	3
Image Unexpectedly Split Across Multiple Pages (600 DPI) with CorelDRAW 12.....	3
Printer Driver Installation	4
New Driver Install.....	4
Existing Drivers	4
Use of Standard TCP/IPv6	4

Release Content

This release is provided to fix SPARs. The fixed SPARs are listed in the next section.

This 13.0.7 release is provided with English, German, French, Italian, Spanish, and Portuguese languages. Russian is not included.

The format is different from previous customer CDs. To install, use either the 64Bit or 32Bit folder.

New or Changed in this Release

This release adds the following:

- SPAR fixes
- The new Xerox branding
- A new **Default All** button which resets all settings to the factory default
- When the driver is installed from a share on a server, the default settings are copied from the server driver instead of using the factory defaults.
- When the driver is installed from a share on a server, the **Default** and **Default All** buttons use the settings from the server instead of the factory defaults
- There may be a delay of several seconds to a minute from the time **OK** or **Apply** is clicked on the server to the time the new settings are available to a client clicking **Default** or **Default All**
- When the driver is installed from a share on a server, bidirectional communications now work on the client
- When clicking on **Enter User Name**, focus now moves to the edit field instead of staying on the radio button
- **Enter User Name** used to allow an unlimited number of characters and truncated it at 64; now it only allows 64
- When selecting Fixed scaling, focus now moves to the edit field instead of staying on the radio button

Note

This release does not support Windows 2000.

SPARs fixed in this Release

- 654227125 **Best Fit** and **Any Sheet** have been removed from Application Media Size
- 035503458 Wipeout command in AutoCAD not working

Known Issues

Deleting the Microsoft XPS Document Writer Printer Could Hang WF Printer Drivers

Deleting this in box windows printer could cause printing problems with all Wide Format printers.

Changes to Enable Advanced Printing Feature Checkbox are Propagated between Clients on Remote Printers

Changing the **Enable Advanced Printing Features** checkbox on one client can cause the change to be made on other clients, when both clients are using a shared driver from a server.

Job is Spread Across Multiple Pages

When printing from Excel 2003, certain files cause the message **Margins do not fit page size** to appear and the file will print incorrectly.

Settings on one Driver Propagated to all Printer Drivers

When multiple instances of the HP-GL/2 driver are installed (for example, a 721 and a 6279), some settings from one driver will be propagated to the other Wide Format Drivers. Some settings that have been seen to propagate are DPI, Raster Stamps, Job Label, and Resolution.

Driver Settings are not Saved after Printing from AutoDesk Design Review

Some settings are not preserved from one print to the next when using AutoDesk Design Review.

Image Unexpectedly Split Across Multiple Pages (600 DPI) with CoreDRAW 12

Some files printed at 600 DPI from CoreDRAW 12 will print incorrectly. Changing the resolution to 400 DPI will fix the problem.

Printer Driver Installation

New Driver Install

Follow the procedure in the Xerox FreeFlow Accxes Print Server Drivers and Client Tools Software Installation Guide.

Existing Drivers

All previous versions of Wide Format HP-GL/2 drivers must be removed from the server and/or workstation client before installing this new driver. This includes deleting the printer icon, removing the driver, and then rebooting the operating system. Then, follow the procedure in the Xerox FreeFlow Accxes Print Server Drivers and Client Tools Software Installation Guide.

Use of Standard TCP/IPv6

This driver supports the use of IPv6 on Vista and Server 2008.

