

June 2012

Dear Xerox XC550/560 Integrated Fiery Color Server customer:

Your XC 550/560 Integrated Fiery Color Server can now be upgraded with the **1.1sp2** software patch.

NOTE: *Your system must be at version 1.1 prior to installing this software.*

We tested this software patch specifically for the System Problem Action Requests (SPARs) noted below. If your SPAR number is not listed, we are providing you this software either because you reported a problem that resembles one of the listed fixes or because our testing has shown that this software should resolve your problem. If this software does not resolve your problem, please contact the hotline and provide a detailed job scenario and sample job(s) for further investigation, testing, and resolution.

This software patch contains fixes for the following SPARs:

SPAR #	Description
1. 857040920	JavaScript alert shown during calibration on fx engine.
2. 922132782	Adjust image transfer causes print images to print with low density
3. 158701264	Scan jobs are not generated if color scanning is set to auto detect
4. 574630942	Print queue shows ink waster toner bin full message.
5. 900974701	Some plain media types will not print when media type is set to any in printer driver.

Fixes the following issue that were not in 1.1 but are in 1.0

- **Scan template not holding document setting (601806510)**
- **When scanning using PDF-A template, scanned files comes in as a standard PDF format**
- **Printing specific fonts are lighter than expected**
-

NOTE: *Not all child SPARs will be listed in this letter.*

Prerequisites:

1.1sp1