

READ ME

Xerox XJ+/XJ+325 V3.2/XJ+525 v4.21 3/26/98
NET.03.26.98.ps

PROBLEM:

When printing from NT 4.0 the filename viewed in the Spooler or Command Workstation is limited to 15 characters. This was originally seen in Microsoft Power Point documents.

HOW TO DOWNLOAD THE PATCH:

- 1) Connect Fiery to Ethernet network, either AppleTalk, TCP/IP or IPX.
- 2) Use the "Fiery XJ Downloader" to download the file NET.03.26.98.ps to the direct queue of the Fiery. This patch should be downloaded to the direct queue in order to guarantee that the system is correctly updated.
- 3) After download, print out the "Job Log" in order to confirm the patch was processed without an error.
- 4) Reboot the Fiery. When the message appears "hit any button to enter setup", hit any button. Enter any of the setup options (no changes are required) then exit setup. When exiting setup the Fiery will reboot. Print a document to the Fiery that previously was limited to 15 characters in the filename when viewed in the Fiery Spooler or Command Workstation. Update Completed.

Considerations:

1. Entire application name (Microsoft PowerPoint) will show up and the filename will be condensed: "Microsoft PowerPoint - loneforxerox.ppt" which was longipnameforxerox.ppt.
2. In some cases the username will be appended to the end of the filename or disappear completely.
3. Within the job log - under Document - there is a 26 character limitation. This means that printing from MS Word part of the filename is visible, but under MS PowerPoint only "Microsoft PowerPoint" is visible.