# Xerox® 6279 & 6622 Wide Format IIT Firmware Customer Release Notes



Χ	EROX® and	d XEROX an	d Design®,	6279®, and	6622® are ti	rademarks of	Xerox Corpor	ration in the L	Inited States (	and/or other	countries.

# Table of Contents

. 1 . 1 . 1
1
٠.
. 2
. 2
. 2
. 2
. 2
. 2
. 3
. 3
. 3

# Customer Release Notes

# Introduction

The  $Xerox^{\circ}$  6279 & 6622 IIT Firmware Release V1.3.01 provides updated firmware for the scanner used on the 6279 and 6622 products.

This document presents the following information about the firmware release.

- Release deliverables
- Recommended configurations
- Installation procedures
- Customer problems resolved

# Release Deliverables

#### Xerox 6279 & 6622 Wide Format Solution

The following executable is provided for the Xerox 6279 & 6622 Wide Format Solution.

• 6279\_6622\_1.3.01\_IIT.bin (file size = 1,704,318 bytes)



# Recommended Configurations

This firmware can be installed in either 6279 or 6622 scanner (product codes LXT and VBW). The software supports both IIT main boards 960K43410 or 960K43412 (IIT Tag #305 )

If firmware older than 1.3.1 is installed in 960K43412, error code "062-326 IIT BKG SDRAM2 / Check NG" will occur. To resolve this error code, simply load this firmware (6279\_6622\_1.3.01\_IIT.bin).

## Release Installation

#### Print From USB (For Accxes V15.0 and greater)

Place the firmware file onto a USB drive and insert into one of the USB ports on the controller or UI. Choose the "Print From Device" service and select the file on the USB drive to request that it be submitted/printed. A status sheet will be printed to indicate that the download was successful.

#### **Accxes Client Tools**

Download the file named "6279\_6622\_1.3.01\_IIT.bin". A status sheet will be printed and indicate that the download was successful.

#### Web Printer Management Tool

Select Utilities > Upload > <u>Upload File</u>. Use the Browse button to select the "6279\_6622\_1.3.01\_IIT.bin". Click on the "Upload" button. A printed status sheet will indicate that the download was successful.

#### **UNIX**®

Download the software using LPR with the following command line:

lpr -P printername "6279\_6622\_1.3.01\_IIT.bin"

A status sheet will be printed and indicate that the download was successful.

# **New Features**

### Support for new (960K43412) IIT Main Board

This firmware will support both (960K43410 or 960K43412 ) of the IIT main boards.

# Customer Issues Resolved

The following issues were resolved in V1.3.01 (since V1.2.3).

Issue Description	Problem			
Accxes communication	A system hang could occur if the document being scanned did not compress well.			
Background removal	Previous algorithm favored the right edge 210 mm instead of the whole width of the document.			